



CAUTION

Change to UL Standard (UL508C)

The UL standard (UL508C) has been changed and now IFR (reevaluation of registered products) is necessary. As a result, it is no longer necessary to use "Class 2 power supplies" as drive sources for motors. Use of "Class 2 power supplies" has been specified in the manuals under the old standard, but this requirement is no longer applicable.

Our products have been certified under the old UL508C standard on the condition of use of "Class 2 power supplies." With the recent change to the standard, we are currently receiving evaluation and certification tests on our products again.

Please be aware and understand that until these tests are complete, our products are considered as those not equipped with motor overload protection.

Note that our internal evaluation tests results meet the requirements for "Short Circuit Test" specified in 20.1.3 (b) of UL508C.

If you require UL508C certification, your system must receive a certification test. When you conduct a certification test, please remember that your IAI product is not equipped with motor overload protection.

For information on when your IAI product will be recertified, please contact IAI.

IAI America, Inc.

ME0247-1A 2/15/2010